HISTORIG AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Ingleside (Hewlings, T. B. A., Villa) (Stoddard Baptist Home) 1818 Newton Street, N. W. Washington District of Columbia HABS No. DC 502

Jack E. Boucher, Photographer June 1985

- 1. VIEW LOOKING SOUTHEAST
- 2. VIEW LOOKING NORTHEAST
- 3. ENTRANCE HALL, LOOKING NORTHEAST, SHOWING ORIGINAL FRESCO SECCO
- 4. MAIN HALL, LOOKING EAST, SHOWING ORIGINAL FRESGO SECCO
- 5. DRAWING ROOM MANTELPIECE, LOOKING NORTHEAST
 Photocopy of circa 1980 photograph in possession of Oudens & Knoop,
 6. Architects, 1320 19th St, N.W., Washington, D. C.
- 66. WEST MANTELPIECE OF DRAWING ROOM
 Photocopy of circa 1980 photograph in possession of Oudens & Knoop.
- 7. DRAWING ROOM CHANDELIER, LOOKING NORTH
 Photocopy of circa 1980 photograph in possession of Oudens & Knoop.
- 8. DINING ROOM MANTELPIECE, LOOKING NORTHEAST
 Photocopy of circa 1980 photograph in possession of Oudens & Knoop.
- 9. SOUTH ERONT Photocopy of circa 1860 photograph in the Athenaeum of Philadelphia.
- 10. WEST (AT LEFT) AND EAST ELEVATIONS DATED FEBRUARY 5, 1851
 Photocopy of drawing by Thomas Ustick Walter in the Athenaeum of
 Philadelphia, 219 South Sixth Street, Philadelphia, Pennsylvania.

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO: HABS DC-502

INGLESIDE

(T. B. A. Hewlings Villa) (Stoddard Baptist Home) 1818 Newton Street Northwest Washington District of Columbia

Photographs HABS DC-502-1 through HABS DC-502-10 were previously transmitted to Library of Congress.

INDEX TO COLOR TRANSPARENCIES

Jack E. Boucher, photographer

DC-502-11 (C'	Γ) Mair	ı Hall, Looking	East, Showing	g Original	Fresco Secco	color

duplicate of dc4)

DC-502-12 (CT) View of Room Interior

DC-502-13 (CT) View of Room Interior